<u>R22</u>

Page 1 of 2

SERVICE BULLETIN SB-87

DATE: 15 December 1999

2901 Airport Drive, Torrance, California 90505

TO: All R22 Owners, Operators, and Service Centers

SUBJECT: Seat Belt Anchor Upgrade

ROBINSON Helicopter company

ROTORCRAFT AFFECTED: R22 Helicopters S/N 0002 thru 1979 unless factory overhauled November 1991 or later.

TIME OF COMPLIANCE: By 31 March 2000

BACKGROUND: Since 1991, A348-1 revision I and subsequent seat belt anchors have been heat treated to provide additional strength. Although the earlier non-heat-treated anchors met FAA strength requirements, RHC is requiring all anchors be upgraded to reduce any possibility of a future failure.

COMPLIANCE PROCEDURE:

NOTE: Use R22 Maintenance Manual (MM) change 19 dated 30 June 1999 or later.

- 1. Reference helicopter serial number and order one A348-1 seat belt anchor from RHC Customer Service.
- 2. Remove A445-2 cover between seat bottoms.
- 3. Disconnect A333-1 collective stop from A348-1 seat belt anchor. (If seatback panels are removed, restrain collective from moving beyond normal up limit.)
- 4. Remove A348-1 seat belt anchor with attached seat belt buckle halves.
- 5. Transfer seat belt buckle halves to new seat belt anchor.
- 6. Install new seat belt anchor.
- 7. Connect A333-1 collective stop to seat belt anchor per R22 MM Section 8.212(e).
- 8. Verify collective friction is adjusted per R22 MM Section 8.225. Move collective thru full range of travel and verify no binding.
- 9. Install A445-2 cover.
- 10. Enter installation of A348-1 anchor, including revision letter, in aircraft maintenance records.

Approximate Cost:

- Parts: \$312 deposit, fully refunded if old A348-1 anchor, or photographic evidence of its destruction, is received by RHC prior to 1 June 2000.
- Labor: 0.5 manhour.

THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.