2901 Airport Drive, Torrance, California 90505

■ PHONE (310) 539-0508 ■ FAX (310) 539-5198

R44

Page 1 of 2

SERVICE BULLETIN SB-18

DATE: 16 April 1997

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Pilot's Heater Outlet Air Supply Hose

ROTORCRAFT AFFECTED: R44 Helicopters S/N 0001 through 0317, except 0298, 0301, 0306, 0307, 0311, 0312, 0314 and 0315.

TIME OF COMPLIANCE: Within next 50 flight hours or by 31 May 1997, whichever occurs first.

BACKGROUND: RHC has received one report of the air hose to the pilot's heater outlet shifting and causing interference with the tail rotor control C317-2 bellcrank assembly.

COMPLIANCE PROCEDURE:

1. Reference helicopter serial number and order the following:

R44 Astro: one KI-117 kit

R44 Clipper: one each of MS27039C0807 screw, AN960-8L washer, MS21042L08 nut, and MS21919WDG40 clamp.

- Slide C444 cover assembly to top of cyclic stick and temporarily secure in place.
- Remove avionics from mounting trays. Detach intercom system from C641 avionics face and remove avionics face.
- Remove radio rack (it is not necessary to disconnect airframe wiring from radio 4. trays to remove radio rack).
- On outside centerline of chin, locate head of MS27039C08 screw approximately 15 inches forward of C794-1 forward belly panel. Measure and mark a point 5. three inches aft and three inches to right of screw head. Using care not to damage heater hose, drill a 0.170 inch diameter hole at the marked point. Remove debris.
- Refer to Figure 1. Secure heater hose to chin with MS21919WDG48 clamp (MS21919WDG40 clamp for R44 Clipper), MS27039C0807 screw (screw head outside), AN960-8L washer, and MS21042L08 nut as shown. Move tail rotor pedals through full range of travel and verify clearance between hose and tail rotor controls.
- Install radio rack, avionics face, avionics, and C444 cyclic cover.

Approximate Cost:

1.0 manhour Labor:

No charge if ordered by 31 May 1997. Parts:

Order must include R44 serial number.

