2901 Airport Drive, Torrance, California 90505

■ PHONE (310) 539-0508 ■ FAX (310) 539-5198

R44

Page 1 of 2

SERVICE BULLETIN SB-26

DATE: 31 Jan 1998

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Lateral Cyclic Trim Assembly

ROTORCRAFT AFFECTED: R44 Helicopters S/N 0002 thru 0420 and 0425, 0426, and 0427.

<u>TIME OF COMPLIANCE</u>: Within next 10 flight hours and every 20 flight hours thereafter until C056-1 spring assembly is replaced with Revision H or subsequent. C056-1 must be replaced no later than 31 Mar 1998.

BACKGROUND: RHC has received reports of excessive C585-1 shaft wear. Excessive wear can cause binding of the flight controls. The KI-129 kit contains a redesigned C056-1 spring assembly with Teflon-lined bearings to prevent excessive wear or galling.

COMPLIANCE PROCEDURE:

- 1. Switch cyclic trim system on. Push and hold cyclic stick against right stop until motor stops, then switch trim off. (This will apply maximum right trim.)
- Remove avionics from mounting trays. Detach intercom system from C641 avionics face and remove avionics face.
- 3. Remove radio rack (not necessary to disconnect airframe wiring from radio trays to remove radio rack).
- Move cyclic stick to left stop to compress trim spring and expose upper part of shaft.
- Refer to Figure 1. Measure shaft diameter in several places. If shaft diameter varies more than 0.004 inches in any 0.50 inch of length, C056-1 spring assembly must be replaced before further flight.
- 6. If shaft diameter is within limits specified above, clean and lubricate with A257-1 grease.

- 7. Install radio rack, avionics face, and avionics.
- 8. Order KI-129 Kit (reference helicopter serial number).
- 9. Replace C056-1 spring assembly per kit instructions and enter SB-26 complied with in aircraft logbook. Return old C056-1 spring assembly to RHC.

Approximate Cost:

Labor:

0.5 manhours for inspection.


2.0 manhours for installation of KI-129 kit.

Parts:

\$650 for KI-129 Kit.

\$500 refund if old parts returned to RHC by 28 Feb 98.

(\$650 refund if under warranty).



THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.