2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 2

R66 SERVICE BULLETIN SB-12

DATE: 8 December 2014

TO: R66 Owners, Operators, and Maintenance Personnel

SUBJECT: Landing Gear Attach Nuts

ROTORCRAFT AFFECTED: R66 helicopters S/N 0002 thru 0547.

TIME OF COMPLIANCE: Within next 100 flight hours or by 28 February 2015, whichever occurs first.

BACKGROUND: RHC has received a report of a cracked NAS1291-7 nut attaching the landing gear assembly to the helicopter. This bulletin requires replacing NAS1291-7 landing gear attach nuts with D210-7 nuts, drilling a vent hole in each cross tube, and installing clear plastic rain caps to facilitate fastener inspection.

COMPLIANCE PROCEDURE:

- 1. If helicopter is equipped with landing gear having (4) clear plastic rain caps on cross tubes, the requirements of this bulletin have been complied with. Proceed to step 7.
- 2. If helicopter is equipped with landing gear having (4) aluminum rain caps on cross tubes, order (4) D210-7 nuts, (2) C247-3 rain caps, (2) F411-9 rain caps, and B270-1 sealant as required.
- 3. Using plastic scraper, remove sealant securing aluminum C247-2 and F411-6 rain caps to cross tubes. Remove and discard rain caps.
- 4. Using back-up wrench, loosen NAS1291-7 nuts attaching landing gear assembly to helicopter, but do not remove nuts. Hoist helicopter per R66 Maintenance Manual (MM) § 7-20. Remove and discard NAS1291-7 nuts and install (4) D210-7 nuts. Special torque fasteners to 66 ft-lb and torque stripe per MM Figure 2-1. Lower helicopter.
- 5. Refer to Figure 1. Lay out vent hole location on left side of F241-3 (aft) cross tube and left side of F241-4 (forward) cross tube as shown. Drill one 0.128 inch diameter hole in each cross tube and deburr. Clean up debris.
- 6. Install (2) C247-3 rain caps on aft cross tube and (2) F411-9 caps on forward cross tube (one cap each end, painted side against cross tube, window up) using B270-1 adhesive. Remove excess adhesive and allow to cure.
- 7. Make appropriate maintenance record entries.


APPROXIMATE COST:

Parts:	(4) D210-7 nut \$	$14.00 \ each = $$	56.00
	(2) C247-3 cap \$	$8.00 \; \text{each} = \$$	16.00
	(2) F411-9 cap \$	$8.00 \; \text{each} = \$$	16.00
	(1) B270-1 sealant \$	28.50 each = \$	28.50

Total: \$ 116.50

Procure parts from any R66 Dealer or Service Center, or order directly from RHC Customer Service via email, fax, or phone.

Labor: 3.0 man-hours.






FIGURE 1

THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.