

2901 Airport Drive, Torrance, California 90505

Phone(310) 539-0508 Fax (310) 539-5198

## **R22 SERVICE LETTER SL-57**

Page 1 of 1

## **R44 SERVICE LETTER SL-34**

DATE: 22 February 2008

TO: R22 and R44 Owners, Operators, and Service Centers

**SUBJECT:** Alternator V-Belts

**BACKGROUND:** RHC has received reports of alternator V-belts requiring frequent replacement due to heat deterioration. Alternator and air conditioning compressor V-belts that use a different rubber compound are now available which should increase service life.

## COMPLIANCE PROCEDURE:

When replacing alternator and air conditioning compressor V-belts, P/N B173-1 thru -4, install Revision C or later belts.

Note: Unused B173-1 thru -4 Revision A or B V-belts may be returned to RHC Customer Service for exchange.