

R44

SERVICE BULLETIN SB-7A

Page 1 of 1

DATE: 06 June 1995 **REV:** 08 June 1995

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Low RPM Warning Unit Adjustment

ROTORCRAFT AFFECTED: R44 helicopters S/N 0001 thru 0183 and S/N 0189

TIME OF COMPLIANCE: By 30 June 1995

BACKGROUND: To help prevent low rotor RPM accidents, the RPM at which the warning horn operates is being increased to give the pilot additional time to take corrective action.

COMPLIANCE PROCEDURE:

Adjust A569 Low RPM warning unit so that warning horn operates below $97 \pm 1\%$ rotor RPM and turns off above $97 \pm 1\%$ RPM (reference Section 14.200 of R44 Maintenance Manual).

Approximate Cost:

Labor: .2 manhour

Parts: No parts required