

SERVICE LETTER SL-15A

DATE: 02 October 1998 **REV:** 06 October 1998

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Mixture Control Cable Clamp

ROTORCRAFT AFFECTED: All R44 Helicopters

BACKGROUND: To ensure mixture control cannot move without pilot moving mixture control knob, the following check must be performed.

COMPLIANCE PROCEDURE: To be performed by either mechanic or pilot

Locate mixture control cable bracket on engine sump. Cable housing is secured to bracket with AN735-4 clamp. Verify clamp is tight and secure. Push and pull on cable housing to ensure it does not slip in clamp.

APPROXIMATE COST:

Parts: None required

Labor: 0.1 Manhour