

**R44 SERVICE LETTER SL-48**

**DATE:** 01 August 2014

**TO:** R44 II Owners, Operators, and Maintenance Personnel

**SUBJECT:** Precision Airmotive Service Bulletin PRS-109

**ROTORCRAFT AFFECTED:** R44 II helicopters equipped with Precision Airmotive RSA-10AD1 fuel injection servos, also know as fuel control units, originally installed in R44 II helicopters S/N 13458 and prior. (R44 II helicopters S/N 13459 and subsequent, delivered with AVStar servos, are unaffected by the subject service bulletin.)

**BACKGROUND:** Precision Airmotive has issued Service Bulletin PRS-109 in response to worn thrust washers found inside fuel injection servos.

---

**COMPLIANCE PROCEDURE:**

Follow Precision Airmotive Service Bulletin PRS-109 instructions, available online at [www.precisionairmotive.com](http://www.precisionairmotive.com).