2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

R22 SERVICE LETTER SL-69

R44 SERVICE LETTER SL-53

R66 SERVICE LETTER SL-12

DATE: 04 April 2016

TO: R22, R44 & R44 II, and R66 Owners, Operators, and Maintenance Personnel

SUBJECT: Altimeters

BACKGROUND: United Instruments, Inc. has issued Service Bulletin No. 13, which affects certain 5934-series altimeters manufactured between January 2015 and February 2016. Recent production RHC part number A613-1, -2, and -4 altimeters are United Instruments, Inc. part number 5934-series altimeters.

COMPLIANCE PROCEDURE:

- 1. Refer to United Instruments, Inc. Service Bulletin No. 13 instructions, located online at: www.unitedinst.com.
- 2. Refer to helicopter maintenance records and determine if installed altimeter model and serial number is affected. If installed altimeter is not affected, no further action is required.
- 3. If installed altimeter is affected, follow Service Bulletin No. 13 instructions as soon as practical.

NOTE: RHC is not a designated service facility for United Instruments, Inc. Service Bulletin No. 13 repairs.