2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

## **R22 SERVICE LETTER SL-72**

**DATE:** 21 November 2016

**TO:** R22 Owners, Operators, and Maintenance Personnel

**SUBJECT:** New A020-90 & A047-6 Upper Frame Installation

**BACKGROUND:** A020-2 and A047-1 upper frames have been superseded by A020-90 and A047-6 upper frames, which feature an integral inboard support for the A316-1 bellcrank. Approved alteration of existing A314-3 support is required when replacing superseded upper frames.

## **COMPLIANCE PROCEDURE:**

When replacing A020-2 or A047-1 upper frame with A020-9 or A047-6 upper frame, remove and discard A314-7 clip & attaching rivets, and trim upper portion of A314-3 support as shown. Smooth reworked edges and coat bare metal with primer.

