

ROBINSON HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

To: All R22 Dealers, Service Centers and Owners

15 January 2009

Subject: R22 Factory Overhaul Price List

The following overhaul prices are effective for all aircraft arriving at the RHC factory ready for overhaul after 15 January 2009 and apply to properly maintained, undamaged R22 helicopters without excessive corrosion and still in airworthy condition. Upon receipt of the aircraft, including all parts, logbooks, signed work authorization, and a 50% down payment, the aircraft will be disassembled, inspected, and placed on the R22 production line for reassembly. During overhaul, all fatigue-life-limited components with less than 2200 hours remaining are replaced. All engines are overhauled per the current Lycoming overhaul manual by either RHC or Lycoming. The overhaul price includes the following:

| Components Overhauled | Parts Replaced | Parts Replaced (cont.) |
|------------------------------|----------------------------|--|
| A005-5 MR Hub | A014 Skid Tube | A190-2 V-Belts |
| A006-1/-6 MR Gearbox | A016-4 MR Blades | A241-2 Aft Cross Tube |
| A012 Collective & Cyclic | A027 Cooling System Panels | A258-1 Pitch Links |
| A017-2 Swashplate | A029-2 TR Blades | A274 Windshields |
| A018 Clutch | A041-11 Driveshaft Bearing | A667 Skid Shoes |
| A021-1/B021-1 TR Gearbox | A120 Bellcrank | A937-1/-2 Skid Extensions |
| A051-1 Actuator | A121-17 P/P Tube | A947 Flexplates |
| A031-1 TR Pitch Control | A158-1 MR Spindles | Various small parts & hardware |
| A007-5 Fanshaft | A159-1 Pitch Bearings | Interior – includes seats and carpets |
| A062 TR Hub | A169 Muffler | |
| Engine (OH exchange) | A170 Sheave | |

Following reassembly, the aircraft exterior is repainted with a white base and one trim color (other paint options available at additional charge). All R22s overhauled at the factory, including engines, will receive a new RHC one-year or 1000-hour (whichever occurs first) limited warranty. Prices given do not include avionics, instruments, floats, searchlights, or other specialized equipment. Prices for the basic overhaul and upgrades are listed below. Prices on the 4400-hour overhauls will vary on additional items, including life-limited parts, requiring replacement.

Base Price depending
\$130,000.00 + upgrades

Basic Overhaul Price

All R22 Models

Upgrades

| Aircraft S/N | Description | Price |
|---------------------|---|--------------|
| Required thru 0747 | B223/B224 TR Driveshaft | \$ 1,651.00 |
| Required thru 2520 | A758-5/-6 RPM Governor | \$ 4,051.00 |
| Required thru 2520 | A758-5/-6 RPM Governor (B029-1 currently installed) | \$ 682.00 |
| Required | B338-2 ICS Audio Control (w/ music) | \$ 1,080.00 |
| Required | KI-160 Full Flow Oil Filter | \$ 850.00 |
| Mariners | A949-1/-2 Float Replacement | \$11,700.00 |
| Optional | C058-5 Cyclic Pistol Grip | \$ 2,750.00 |

Additional upgrades may be required on R22 S/N 0500 and prior

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs3@robinsonheli.com.