

To: All R22 Dealers, Service Centers and Owners

15 January 2010

Subject: R22 Factory Overhaul Price List

The following overhaul prices are effective for all aircraft arriving at the RHC factory ready for overhaul after 15 January 2010 and apply to properly maintained, undamaged R22 helicopters without excessive corrosion and still in airworthy condition. Upon receipt of the aircraft, including all parts, logbooks, signed work authorization, and a 50% down payment, the aircraft will be disassembled, inspected, and placed on the R22 production line for reassembly. During overhaul, all fatigue-life-limited components with less than 2200 hours remaining are replaced. All engines are overhauled per the current Lycoming overhaul manual by either RHC or Lycoming. The overhaul price includes the following:

Components Overhauled	Parts Replaced	Parts Replaced (cont.)
A005-5 MR Hub	A014 Skid Tube	A190-2 V-Belts
A006-1/-6 MR Gearbox	A016-4 MR Blades	A241-2 Aft Cross Tube
A012 Collective & Cyclic	A027 Cooling System Panels	A258-1 Pitch Links
A017-2 Swashplate	A029-2 TR Blades	A274 Windshields
A018 Clutch	A041-11 Driveshaft Bearing	A667 Skid Shoes
A021-1/B021-1 TR Gearbox	A120 Bellcrank	A937-1/-2 Skid Extensions
A051-1 Actuator	A121-17 P/P Tube	A947 Flexplates
A031-1 TR Pitch Control	A158-1 MR Spindles	Various small parts & hardware
A007-5 Fanshaft	A159-1 Pitch Bearings	Interior – includes seats and carpets
A062 TR Hub	A169 Muffler	
Engine (OH exchange)	A170 Sheave	

Following reassembly, the aircraft exterior is repainted with a white base and one trim color (other paint options available at additional charge). All R22s overhauled at the factory, including engines, will receive a new RHC one-year or 1000-hour (whichever occurs first) limited warranty. Prices given do not include avionics, instruments, floats, searchlights, or other specialized equipment. Prices for the basic overhaul and upgrades are listed below. Prices on the 4400-hour overhauls will vary on additional items, including life-limited parts, requiring replacement.

Base Price depending

Basic Overhaul Price All R22 Models \$134,000.00 + upgrades

Upgrades

Aircraft S/N	Description	Price
Required thru 0747	B223/B224 TR Driveshaft	\$ 1,750.00
Required thru 2520	A758-5/-6 RPM Governor	\$ 4,130.00
Required thru 2520	A758-5/-6 RPM Governor (B029-1 currently installed)	\$ 682.00
Required	B338-2 ICS Audio Control (w/ music)	\$ 1,080.00
Required	KI-160 Full Flow Oil Filter	\$ 850.00
Mariners	A949-1/-2 Float Replacement	\$11,700.00
Optional	C058-5 Cyclic Pistol Grip	\$ 2,750.00

Additional upgrades may be required on R22 S/N 0500 and prior

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs3@robinsonheli.com.