

R44

SERVICE BULLETIN SB-6

Page 1 of 1

DATE: 23 May 1995

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Placard to Prohibit Pushovers

ROTORCRAFT AFFECTED: R44 helicopters S/N 0001 thru 0206

TIME OF COMPLIANCE: Prior to next flight

BACKGROUND: It has been determined that the risk involved in demonstrating low-G maneuvers in the air is too great. To insure that no intentional low-G pushover maneuvers will be performed, a placard is to be placed on the cyclic stick prohibiting such maneuvers.

COMPLIANCE PROCEDURE:

Clean area of cyclic control and install A654-83 decal in clear view of pilot as shown below (decal enclosed with service bulletin to aircraft owners).

