

R44

Page 1 of 1

SERVICE BULLETIN SB-30

DATE: 28 October 1998

TO: All R44 Owners, Operators, and Service Centers

SUBJECT: Auxiliary Fuel Tank Drain Tube Shutoff Clamp


ROTORCRAFT AFFECTED: R44 Helicopters S/N 0002 thru 0529 except 0440, 0485, 0512, 0515, 0519, 0526, 0527, and 0528.

TIME OF COMPLIANCE: By 30 November 1998.

BACKGROUND: RHC has added a shutoff clamp to the auxiliary fuel tank drain tube as a redundant seal when the tube is stowed for flight and a decal to ensure proper use of the auxiliary tank drain.

COMPLIANCE PROCEDURE:

Open D663-1 shutoff clamp and slide onto A729-7 tube as shown. (It may be necessary to deflect clamp open slightly for tube to enter.) Install A654-93 decal as shown. (Shutoff clamp and decal are enclosed. Additional shutoff clamps and decals may be ordered from RHC customer service.)



Approximate Cost:

Parts: No charge.

Labor: 0.1 manhour.

THE DESIGN ENGINEERING ASPECTS OF THIS BULLETIN HAVE BEEN SHOWN TO COMPLY WITH APPLICABLE FEDERAL AVIATION REGULATIONS AND ARE FAA APPROVED.