

**R66 SERVICE LETTER SL-08**

**DATE:** 09 May 2014

**TO:** R66 owners and operators intending to register aircraft in EASA Member States

**SUBJECT:** EASA Registration Requirements

**ROTORCRAFT AFFECTED:** R66 helicopters S/N 0004 thru 0559.

**BACKGROUND:** The European Aviation Safety Agency (EASA) requires specific hardware in certain locations on R66 helicopters registered in EASA Member States.

---

**COMPLIANCE PROCEDURE:**

For affected aircraft that are to be registered in an EASA Member State, order one KI-227 kit. Replace hardware per kit instructions. Note that the hydraulic servos must be returned to RHC for hardware replacement.

Note: KI-227 is available only to R66 dealers in EASA Member States. Dealer must provide helicopter serial number.