2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

R66 SERVICE LETTER SL-16

DATE: 07 November 2016

TO: R66 Owners, Operators, and Maintenance Personnel

SUBJECT: Garmin G500H EFIS Air Temperature Probe Relocation

BACKGROUND: A kit is available for R66 helicopters with earlier G500H LRU (EFIS) (shown in helicopter's RHC-issued POH Equipment List as Part No. F817-1) to relocate the GTP 59 temperature probe, which in its original location could be damaged when making a sharp turn using the MT900/MT950 tow cart.

COMPLIANCE PROCEDURE:

Refer to helicopter's R66 Pilot's Operating Handbook Section 6 and locate RHC-issued Equipment List. If listed Garmin G500H LRU is Part No. F817-1, order one KI-243 kit from RHC Customer Service and install per kit instructions. Part No. F817-3 installations do not require probe relocation.