

# ROBINSON HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

## Pricing for R22 2200-Hour Maintenance and Inspection Performed at RHC

Below pricing for R22 2200-Hour Maintenance and Inspection performed at RHC is effective 15 January 2017. Base price is for an airworthy R22 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2200 hours:

### Exchange Components

### New Parts

A006 MR Gearbox	A016 MR Blades	A170 Sheave
A012 MR Flight Controls	A027 Cooling System Panels	A190 Drive V-Belts
A013 TR Flight Controls	A029 TR Blades	A258 MR Pitch Links
A017 Swashplate	A031 TR Pitch Control	A274 Windshields
A018 Clutch	A041 Damper Bearing	A667 Skid Shoes
B021 TR Gearbox	A120 Bellcrank	A947 Flex Plates
A051 Actuator	A121-17 P/P Tube	A007 Fan Shaft & Bearing
A062 TR Hub	A158 Spindles	A005 MR Hub
B174 Fanwheel	A159 Pitch Bearings	Various small parts & hardware
Engine	A169 Muffler	

### Base Price for R22 2200-Hour Maintenance & Inspection (does not include upgrades)

All R22 Models ..... \$151,000.00 + upgrades

### Upgrades

Applicability*	Description	Price
Required	B338 ICS Control (VOX & music Input)	\$ 1,520.00
Required	Full-Flow Oil Filter	\$ 950.00
Required	Fuel Bladder Installation	\$ 6,400.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Mariners	A949 Float Replacement (both)	\$14,000.00
Optional	C058 Cyclic Pistol Grip	\$ 3,170.00
Optional, S/N's 0501 thru 2570	Lycoming O-320 to O-360 (new) Engine, Exchange	\$34,000.00

### Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$680.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.

**KI-218 FULL THROTTLE CAUTION LIGHT UPGRADE**

**EFFECTIVE JANUARY 15, 2017**

**R22 SL #66**

KI-218-1A \$190.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-1B \$540.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven SL #52**

KI-218-2A \$190.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-2B \$510.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven II without Air Conditioning**

KI-218-3A \$610.00 If Throttle Bellcrank doesn't include A534-1 Stop  
KI-218-3B \$210.00 If Throttle Bellcrank includes A534-1 Stop

**R44 Raven II with Air Conditioning**

KI-218-3C \$190.00

**ROBINSON  
HELICOPTER COMPANY**

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

**4400-HOUR PARTS**

**EFFECTIVE JANUARY 15, 2017**

**R22 Beta & Beta II**

A020-90 (replaces A020-2) Upper Frame \$4,700.00  
A023-22 \$5,020.00  
A023-23 Tailcone \$5,020.00  
A046-2 Lower R/H Frame \$2,060.00  
A062-1 TR Hub \$1,240.00  
A154-1 MR Hub \$1,460.00

**R44 Astro, Raven & Raven II**

C023-1 STD Tailcone \$6,770.00  
C023-4 Tailcone, ENG \$9,750.00  
C023-14 Tailcone, 5 Antenna Mounts \$6,970.00  
C023-15 Tailcone, 3 Antenna Mounts & VOR Antennas \$6,870.00  
C044-1 Horizontal Stabilizer \$2,570.00

**R66 Turbine**

Not applicable as all life-limited parts time out at 2000 hours.