

Pricing for R22 2200-Hour Maintenance and Inspection Performed at RHC

Below pricing for R22 2200-Hour Maintenance and Inspection performed at RHC is effective **01 July 2018**. Base price is for an airworthy R22 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2200 hours:

Exchange Components

New Parts

| | | |
|-------------------------|----------------------------|--------------------------------|
| A006 MR Gearbox | A016 MR Blades | A170 Sheave |
| A012 MR Flight Controls | A027 Cooling System Panels | A190 Drive V-Belts |
| A013 TR Flight Controls | A029 TR Blades | A258 MR Pitch Links |
| A017 Swashplate | A031 TR Pitch Control | A274 Windshields |
| A018 Clutch | A041 Damper Bearing | A667 Skid Shoes |
| B021 TR Gearbox | A120 Bellcrank | A947 Flex Plates |
| A051 Actuator | A121-17 P/P Tube | A007 Fan Shaft & Bearing |
| A062 TR Hub | A158 Spindles | A005 MR Hub |
| B174 Fanwheel | A159 Pitch Bearings | Various small parts & hardware |
| Engine | A169 Muffler | |

Base Price for R22 2200-Hour Maintenance & Inspection (does not include upgrades)

All R22 Models \$155,000.00 + upgrades

Upgrades

| Applicability* | Description | <u>Price</u> |
|--------------------------------|---|---------------------|
| Required | B338 ICS Control (VOX & music Input) | \$ 1,560.00 |
| Required | Full-Flow Oil Filter | \$ 1,000.00 |
| Required | Fuel Bladder Installation | \$ 6,400.00 |
| Required | KI-218 Full Throttle Caution Light (see attached for pricing) | |
| Mariners | B900 Float Replacement (both) | \$14,300.00 |
| Optional | C058 Cyclic Pistol Grip | \$ 3,230.00 |
| Optional, S/N's 0501 thru 2570 | Lycoming O-320 to O-360 (new) Engine, Exchange | \$35,000.00 |

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$810.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.