

**Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC**

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC is effective 15 January 2018. Base price is for an airworthy R44 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour Overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200 hours:

<b>Exchange Components</b>	<b>New Parts</b>	
C006 MR Gearbox	A120 Bellcrank	C169 Muffler
C012 MR Flight Controls	A190 Drive V-Belts	C170 Sheave
C013 TR Flight Controls	C008 TR Assembly	C258 Pitch Links
C017 Swashplate	C016 MR Blades	C274 Windshields
C018 Clutch	C020 Upper Frame	C667 Skid Shoes
C021 TR Gearbox	C027 Cooling Panels	C947 & A947 Flex Plates
C051 Actuator	C121-17 P/P Tube	D079 TR Guard
D174 Fanwheel	C005 MR Hub	D224 TR Driveshaft
Engine	C158 MR Spindles	C031 TR Pitch Control
	C159 Pitch Bearings	C007-5 Fan Shaft & Bearing
		Various small parts & hardware

**Base Price for R44 2200-Hour Maintenance & Inspection (does not include upgrades)**

<b>R44 Raven I/Cadet.....</b>	<b>\$220,000.00 + upgrades</b>
<b>R44 Raven II.....</b>	<b>\$235,000.00 + upgrades</b>

**UPGRADES**

<b><u>Applicability*</u></b>	<b><u>Description</u></b>	<b><u>Price</u></b>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$46,000.00
Required	Full-Flow Oil Filter	\$ 1,000.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	D575 Pneumatic Front Door Opener	\$ 9,950.00
Optional	C058 Cyclic Pistol Grip	\$ 3,330.00
Required	C034 Pop-Out Float Overhaul (includes new floats, covers & cylinder exchange)	\$36,000.00
Required	C949 Utility Float Replacement	\$20,500.00
Required	Fuel Bladder Installation	\$ 6,800.00
Optional, 10001 & subsequent	Air Conditioning	\$19,600.00

\*Unless previously installed

**Base price also includes:**

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$1,740.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.

**KI-218 FULL THROTTLE CAUTION LIGHT UPGRADE**

**EFFECTIVE 15 JANUARY 2018**

**R22 SL #66**

KI-218-1A \$195.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-1B \$550.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven SL #52**

KI-218-2A \$200.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-2B \$550.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven II without Air Conditioning**

KI-218-3A \$640.00 If Throttle Bellcrank doesn't include A534-1 Stop  
KI-218-3B \$230.00 If Throttle Bellcrank includes A534-1 Stop

**R44 Raven II with Air Conditioning**

KI-218-3C \$200.00

**4400-HOUR PARTS**

**EFFECTIVE 15 JANUARY 2018**

**R22 Beta & Beta II**

A020-90 (replaces A020-2) Upper Frame \$4,790.00  
A023-22 \$5,120.00  
A023-23 Tailcone \$5,120.00  
A046-2 Lower R/H Frame \$2,100.00  
A062-1 TR Hub \$1,260.00  
A154-1 MR Hub \$1,490.00

**R44 Astro, Raven & Raven II**

C023-1 STD Tailcone \$6,910.00  
C023-4 Tailcone, ENG \$9,950.00  
C023-14 Tailcone, 5 Antenna Mounts \$7,110.00  
C023-15 Tailcone, 3 Antenna Mounts & VOR Antennas \$7,010.00  
C044-1 Horizontal Stabilizer \$2,710.00

**R66 Turbine**

Not applicable as all life-limited parts time out at 2000 hours.