

ROBINSON HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC is effective 15 January 2017. Base price is for an airworthy R44 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour Overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200 hours:

Exchange Components

C006 MR Gearbox
C012 MR Flight Controls
C013 TR Flight Controls
C017 Swashplate
C018 Clutch
C021 TR Gearbox
C051 Actuator
D174 Fanwheel
Engine

New Parts

A120 Bellcrank
A190 Drive V-Belts
C008 TR Assembly
C016 MR Blades
C020 Upper Frame
C027 Cooling Panels
C121-17 P/P Tube
C005 MR Hub
C158 MR Spindles
C159 Pitch Bearings
C169 Muffler
C170 Sheave
C258 Pitch Links
C274 Windshields
C667 Skid Shoes
C947 & A947 Flex Plates
D079 TR Guard
D224 TR Driveshaft
C031 TR Pitch Control
C007-5 Fan Shaft & Bearing
Various small parts & hardware

Base Price for R44 2200-Hour Maintenance & Inspection (does not include upgrades)

R44 Raven I\$218,000.00 + upgrades
R44 Raven II\$232,000.00 + upgrades

UPGRADES

<u>Applicability*</u>	<u>Description</u>	<u>Price</u>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$45,000.00
Required	Full-Flow Oil Filter	\$ 950.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	D575 Pneumatic Front Door Opener	\$ 6,000.00
Optional	C058 Cyclic Pistol Grip	\$ 3,260.00
Required	C034 Pop-Out Float Overhaul (if received, includes new floats, covers & cylinder exchange)	\$35,200.00
Required	C949 Utility Float Replacement (if received)	\$19,800.00
Required	Fuel Bladder Installation	\$ 6,800.00
Optional, 10001 & subsequent	Air Conditioning	\$19,600.00

*Unless previously installed

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$1,480.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.

KI-218 FULL THROTTLE CAUTION LIGHT UPGRADE

EFFECTIVE JANUARY 15, 2017

R22 SL #66

KI-218-1A \$190.00 If Throttle Bellcrank includes A607-2 Cam
KI-218-1B \$540.00 If Throttle Bellcrank doesn't include A607-2 Cam

R44 Raven SL #52

KI-218-2A \$190.00 If Throttle Bellcrank includes A607-2 Cam
KI-218-2B \$510.00 If Throttle Bellcrank doesn't include A607-2 Cam

R44 Raven II without Air Conditioning

KI-218-3A \$610.00 If Throttle Bellcrank doesn't include A534-1 Stop
KI-218-3B \$210.00 If Throttle Bellcrank includes A534-1 Stop

R44 Raven II with Air Conditioning

KI-218-3C \$190.00

**ROBINSON
HELICOPTER COMPANY**

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

4400-HOUR PARTS

EFFECTIVE JANUARY 15, 2017

R22 Beta & Beta II

A020-90 (replaces A020-2) Upper Frame \$4,700.00

A023-22 \$5,020.00

A023-23 Tailcone \$5,020.00

A046-2 Lower R/H Frame \$2,060.00

A062-1 TR Hub \$1,240.00

A154-1 MR Hub \$1,460.00

R44 Astro, Raven & Raven II

C023-1 STD Tailcone \$6,770.00

C023-4 Tailcone, ENG \$9,750.00

C023-14 Tailcone, 5 Antenna Mounts \$6,970.00

C023-15 Tailcone, 3 Antenna Mounts & VOR Antennas \$6,870.00

C044-1 Horizontal Stabilizer \$2,570.00

R66 Turbine

Not applicable as all life-limited parts time out at 2000 hours.