

# ROBINSON HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

## Pricing for R66 2000-Hour Maintenance and Inspection Performed at RHC

Below pricing for R66 2000-Hour Maintenance and Inspection performed at RHC is effective 15 January 2017. Base price is for an airworthy R66 Turbine helicopter without optional equipment. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4000 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes RR300 engine 2000-Hour Preventative Maintenance Inspection (PMI) performed by a Rolls-Royce Authorized Maintenance, Repair & Overhaul Center (AMROC) and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2000 hours:

### Overhaul Exchange Components

- C005 MR Blade & Spindle Assembly (set)
- C021 TR Gearbox
- C031 TR Pitch Control
- C649 MR Gearbox Oil Cooler
- F001 MR Gearbox Sub-Assembly  
Includes:
  - C017 Swashplate
  - D211 Hydraulic Reservoir
  - D212 Hydraulic Servos
  - D500 Pump Assemblies
  - F006 MR Gearbox
  - G201 Servo Support Frame (new)
- F018 Clutch
- F649 Engine Oil Cooler
- F792 Dual Tachometer

### New Parts

- A120 Bellcrank
- A522 Control Cables
- A947 Flex Plates
- B345 TR Pitch Links
- C005 MR Hub
- C008 TR Assembly
- C023 Tailcone
- C044 Horizontal Stabilizer
- C522 Control Cables
- C947 Flex Plates
- D224 TR Drive Shaft
- F020 Upper Frame
- F173 Exhaust Support Struts
- F235 Upper Frame Struts
- F252 Upper Frame Strut
- F642 Engine Shaft Weldment
- Various small parts & hardware

### BASE PRICE FOR R66 2000-HOUR MAINTENANCE AND INSPECTION PERFORMED AT RHC

**R66 Turbine helicopter ..... \$301,000.00**

### Base price also includes:

- Complete refurbishing of helicopter interior including fresh primer, new seats, new cyclic, and collective boots, new carpet, and new headliner.
- Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).
- Production-equivalent minor upgrades.
- Up-to-date Service Bulletin compliance.
- RHC one-year or 1000-hour (whichever occurs first) limited warranty.

### For an additional charge:

- Optional equipment, or equipment provision, installations.
- DER-approved repairs.

**ROBINSON  
HELICOPTER COMPANY**

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

---

**4400-HOUR PARTS**

**EFFECTIVE JANUARY 15, 2017**

**R22 Beta & Beta II**

*A020-90 (replaces A020-2) Upper Frame \$4,700.00*  
*A023-22 \$5,020.00*  
*A023-23 Tailcone \$5,020.00*  
*A046-2 Lower R/H Frame \$2,060.00*  
*A062-1 TR Hub \$1,240.00*  
*A154-1 MR Hub \$1,460.00*

**R44 Astro, Raven & Raven II**

*C023-1 STD Tailcone \$6,770.00*  
*C023-4 Tailcone, ENG \$9,750.00*  
*C023-14 Tailcone, 5 Antenna Mounts \$6,970.00*  
*C023-15 Tailcone, 3 Antenna Mounts & VOR Antennas \$6,870.00*  
*C044-1 Horizontal Stabilizer \$2,570.00*

**R66 Turbine**

Not applicable as all life-limited parts time out at 2000 hours.