

**Pricing for R22 2200-Hour Maintenance and Inspection Performed at RHC**

Below pricing for R22 2200-Hour Maintenance and Inspection performed at RHC is effective **15 January 2019**. Base price is for an airworthy R22 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400 hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2200 hours:

**Exchange Components**

**New Parts**

A006 MR Gearbox	A016 MR Blades	A170 Sheave
A017 Swashplate	A027 Cooling System Panels	A190 Drive V-Belts
A018 Clutch	A029 TR Blades	A258 MR Pitch Links
B021 TR Gearbox	A031 TR Pitch Control	A274 Windshields
A051 Actuator	A041 Damper Bearing	A667 Skid Shoes
B174 Fanwheel	A120 Bellcrank	A947 Flex Plates
Engine	A121-17 P/P Tube	A007 Fan Shaft & Bearing
	A158 Spindles	Various small parts & hardware
	A159 Pitch Bearings	
	A169 Muffler	

**Base Price for R22 2200-Hour Maintenance & Inspection (does not include upgrades)**

**All R22 Models ..... \$157,000.00 + upgrades**

**Upgrades**

<b>Applicability*</b>	<b>Description</b>	<b>Price</b>
Required	B338-2 ICS Control (VOX & music Input)	\$ 1,780.00
Required	KI-160 Full-Flow Oil Filter	\$ 1,050.00
Required	KI-217-1 Fuel Bladder Tanks	\$ 6,400.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Mariners	B900-6 Float Replacement (both)	\$14,600.00
Optional	C058-5 Cyclic Pistol Grip	\$ 3,320.00
Optional, S/N's 0501 thru 2570	Lycoming O-320 to O-360 (new) Engine, Exchange	\$37,000.00

**Base price also includes:**

Complete refurbishing of helicopter interior including new seats (velour), carpet, and headliner. Additional cost for leather seats is \$810.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

RHC one-year or 1000-hour (whichever occurs first) limited warranty.

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs1@robinsonheli.com.

**KI-218 FULL THROTTLE CAUTION LIGHT UPGRADE**

**EFFECTIVE 15 JANUARY 2019**

**R22 SL #66**

KI-218-1A \$201.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-1B \$567.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven SL #52**

KI-218-2A \$210.00 If Throttle Bellcrank includes A607-2 Cam  
KI-218-2B \$565.00 If Throttle Bellcrank doesn't include A607-2 Cam

**R44 Raven II without Air Conditioning**

KI-218-3A \$660.00 If Throttle Bellcrank doesn't include A534-1 Stop  
KI-218-3B \$240.00 If Throttle Bellcrank includes A534-1 Stop

**R44 Raven II with Air Conditioning**

KI-218-3C \$210.00