

2901 Airport Drive, Torrance, California 90505

Page 1 of 1

## **R66 SERVICE BULLETIN SB-32**

DATE: 29 July 2019

- **TO:** R66 Owners, Operators, and Maintenance Personnel
- **SUBJECT:** Lithium-Ion Battery Sense Wire

**EFFECTIVITY:** R66 Helicopters S/N 0817 thru 0933, excluding 0912 and 0918, if equipped with lithium-ion main battery.

- TIME OF COMPLIANCE: By 31 October 2019.
- **BACKGROUND:** RHC has determined that diodes in the sense wire for the lithium-ion battery may prevent battery heater activation in cold weather. This bulletin requires revising the sense wire diodes.

## **COMPLIANCE PROCEDURE:**

- 1. For each affected helicopter, order one KI-266 Lithium-Ion Battery Installation Diode Upgrade Kit.
- 2. Revise diodes per kit instructions.
- 3. Make appropriate maintenance record entries.

## APPROXIMATE COST:

Parts: No charge for KI-266 kit if ordered by 31 October 2019.

Labor: 1.0 man-hour.