

Pricing for R22 2200-Hour Maintenance and Inspection Performed at RHC

Below pricing for R22 2200-Hour Maintenance and Inspection performed at RHC is effective **15 January 2020**. Base price is for an airworthy R22 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2200-hours:

Exchange Components

New Parts

A006 MR Gearbox	A016 MR Blades	A170 Sheave
A017 Swashplate	A027 Cooling Panels	A190 Drive V-Belts
A018 Clutch	A029 TR Blades	A258 MR Pitch Links
B021 TR Gearbox	A031 TR Pitch Control	A274 Windshields
A051 Actuator	A041 Damper Bearing	A667 Skid Shoes
B174 Fanwheel	A120 Bellcrank	A947 Flex Plates
Engine	A121-17 P/P Tube	A007 Fan Shaft & Bearing
	A158 Spindles	Various small parts & hardware
	A159 Pitch Bearings	
	A169 Muffler	

Base Price for R22 2200-Hour Maintenance & Inspection (does not include upgrades)

All R22 Models **\$160,000.00 + upgrades**

REQUIRED UPGRADES/OPTIONAL EQUIPMENT

Applicability	Description	Price
Required	B338-2 ICS Control (VOX & music Input)	\$ 1,890.00
Required	KI-160 Full-Flow Oil Filter	\$ 622.00
Required	KI-217-1 Fuel Bladder Tanks	\$ 6,400.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Mariners	A034-1 Fixed Float Overhaul (includes new floats)	\$20,000.00
Optional	C058-5 Cyclic Pistol Grip	\$ 3,420.00
Optional, S/N's 0501 thru 2570	Lycoming O-320 to O-360 Engine Upgrade	\$38,000.00

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet (**charcoal only**) and headliner. Additional cost for leather seats is \$810.00.

Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

The RHC limited warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours (whichever occurs first).

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs14@robinsonheli.com.