

Pricing for R44 2200-Hour Maintenance & Inspection Performed at RHC

Below pricing for R44 2200-Hour Maintenance and Inspection performed at RHC is effective **15 January 2020**. Base price is for an airworthy R44 properly maintained, undamaged, and without excessive corrosion. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4400-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes engine 2200-Hour Overhaul performed by RHC or Lycoming and the following fatigue life-limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement of 2200-hours:

Exchange Components

New Parts

C006 MR Gearbox	A120 Bellcrank	C169 Muffler
C017 Swashplate	A190 Drive V-Belts	C170 Sheave
C018 Clutch	C008 TR Assembly	C258 Pitch Links
C021 TR Gearbox	C016 MR Blades	C274 Windshields
C051 Actuator	C020 Upper Frame	C667 Skid Shoes
D174 Fanwheel	C027 Cooling Panels	C947 & A947 Flex Plates
Engine	C121-17 P/P Tube	D079 TR Guard
	C005 MR Hub	D224 TR Driveshaft
	C158 MR Spindles	C031 TR Pitch Control
	C159 Pitch Bearings	C007-5 Fan Shaft & Bearing
		Various small parts & hardware

Base Price for R44 2200-Hour Maintenance & Inspection (does not include upgrades)

R44 Raven I/Cadet (2400-Hours).....	\$230,000.00 + upgrades
R44 Raven II.....	\$247,000.00 + upgrades

REQUIRED UPGRADES/OPTIONAL EQUIPMENT

<u>Applicability</u>	<u>Description</u>	<u>Price</u>
Required thru S/N 0663	Hydraulic Flight Controls (includes pistol grip)	\$49,000.00
Required	KI-163 Full-Flow Oil Filter	\$ 622.00
Required	KI-218 Full Throttle Caution Light (see attached for pricing)	
Optional	D575 Pneumatic Front Door Opener	\$ 9,011.00
Required	C034-5 Pop-Out Float Overhaul (includes new floats, covers & cylinder exchange)	\$30,000.00
Required	C034-4 Fixed Float Overhaul (includes new floats)	\$28,000.00
Required	KI-196-1 or -2 Fuel Bladder Tanks	\$ 6,800.00
Required	Camshaft & Valve Train Parts (flat)	\$ 3,303.00
Required	Camshaft & Valve Train Parts (roller)	\$12,623.00
Optional, 10001 & subsequent	Air Conditioning	\$21,500.00

Base price also includes:

Complete refurbishing of helicopter interior including new seats (velour), carpet (**charcoal only**) and headliner. Additional cost for leather seats is \$1,780.00. Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).

Up-to-date Service Bulletin compliance.

The RHC limited warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours (whichever occurs first).

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs14@robinsonheli.com.