

Pricing for R66 2000-Hour Maintenance and Inspection Performed at RHC

Below pricing for R66 2000-Hour Maintenance and Inspection performed at RHC is effective **15 January 2020**. Base price is for an airworthy R66 Turbine helicopter without optional equipment. Additional maintenance and/or inspections will be required for helicopters with optional equipment, 4000-hours, or if discrepancies are found during helicopter disassembly and evaluation.

Base price includes RR300 engine 2000-Hour Preventative Maintenance Inspection (PMI) performed by a Rolls-Royce Authorized Maintenance, Repair & Overhaul Center (AMROC) and the following fatigue life- limited parts, parts with a recommended time between overhaul (TBO), and parts with a recommended replacement time of 2000-hours:

Exchange Components

- C005 MR Blade & Spindle Assembly (set)
- C021 TR Gearbox
- C031 TR Pitch Control
- C649 MR Gearbox Oil Cooler
- F001 MR Gearbox Sub-Assembly
 - Includes:
 - C017 Swashplate
 - D211 Hydraulic Reservoir
 - D212 Hydraulic Servos
 - D500 Pump Assemblies
 - F006 MR Gearbox
 - G201 Servo Support Frame (new)
- F018 Clutch
- F649 Engine Oil Cooler
- F792 Dual Tachometer

New Parts

- A120 Bellcrank
- A522 Control Cables
- A947 Flex Plates
- B345 TR Pitch Links
- C005 MR Hub
- C008 TR Assembly
- C023 Tailcone
- C044 Horizontal Stabilizer
- C522 Control Cables
- C947 Flex Plates
- D224 TR Drive Shaft
- F020 Upper Frame
- F173 Exhaust Support Struts
- F235 Upper Frame Struts
- F252 Upper Frame Strut
- F642 Engine Shaft Weldment
- Various small parts & hardware

BASE PRICE FOR R66 2000-HOUR MAINTENANCE AND INSPECTION PERFORMED AT RHC

R66 Turbine helicopter \$326,000.00

Base price also includes:

- Complete refurbishing of helicopter interior including new seats, new carpet (**charcoal only**) and new headliner.
- Complete repaint of helicopter exterior including white base with standard trim color (other options available at additional costs).
- Production-equivalent minor upgrades.
- Up-to-date Service Bulletin compliance.

Optional equipment:

- DER-approved repairs.
- C034-4 Fixed float overhaul (includes new floats) \$28,000.00
- C034-5 Pop-out float overhaul (includes new floats, covers & cylinder exchange). \$30,000.00
- RR300 4th stage wheel replacement (SB A-72-024). Determined by vendor when engine is sent in.

The RHC limited warranty covers parts replaced, repaired and/or overhauled for a period of 1-year or 1000-hours (whichever occurs first).

Specifications and prices are subject to change without prior notice. Prices net RHC factory, no Dealer/Service Center discounts apply. For further information, contact cs14@robinsonheli.com.