2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 2

R22 SERVICE LETTER SL-87

R44 SERVICE LETTER SL-73

DATE: 21 August 2020

TO: R22-series, R44, & R44 II Owners, Operators, and Maintenance Personnel

SUBJECT: Main and Tail Gearbox Oil

ROTORCRAFT AFFECTED: All R22-series and R44-series helicopters.

BACKGROUND: RHC has recently transitioned from P/N A257-2 (blue or blue-green) gear oil to P/N A257-22 (semi-clear amber, synthetic) gear oil in R22 & R44 main and tail gearboxes. A257-22 oil is the same oil used on R66 helicopters. A257-22 oil use in new R22 and R44 helicopters is effective:

R22 Helicopters S/N 4825 and subsequent,

R44 Helicopters S/N 2621 and subsequent,

R44 II Helicopters S/N 14398 and subsequent, and

R44 Cadet Helicopters S/N 30069 and subsequent.

Certain gearbox features are required to use A257-22 oil. Older gearboxes should continue to use A257-2 oil. Instructions to ensure appropriate oil type are provided below.

COMPLIANCE PROCEDURE:

- All R22 & R44 gearboxes (including new) may use A257-2 (traditional, blue) oil
 if more convenient or desired. Drain and flush per Maintenance Manual (MM) if
 converting from A257-22 oil.
- 2. Tail gearboxes are eligible for A257-22 oil provided a B563-4 sight gage is installed (refer to Figure 1); not all tail gearboxes can be retrofitted with the B563-4 sight gage (due to thread differences).
- 3. A006 R22 main gearboxes with A146-1 Revision Q & subsequent pinion are eligible for A257-22 oil. A146-1 pinion data plate is adjacent A006 gearbox data plate.
- 4. C006 R44 main gearboxes with C146-2 Revision Q & subsequent pinion are eligible for A257-22 oil. C146-2 pinion data plate is adjacent C006 gearbox data plate.

NOTES:

• Ensure proper decal is installed on aft wall of aux fuel tank (decal will need to be replaced if changing oil types):

R22-series	R44-series
F654-14 decal	F654-13 decal
specifies A257-2	specifies A257-2
(blue) oil	(blue) oil
F654-50 decal	F654-12 decal
specifies A257-22	specifies A257-22
(amber) oil	(amber) oil

- Do not mix A257-22 and A257-2 oil. If inadvertent mixture of oils occurs, drain and flush affected gearbox per MM followed by servicing with correct gearbox oil.
- The same oil should be used in main and tail gearboxes to conform with the appropriate decal above.




FIGURE 1