

R44

Page 1 of 1

SERVICE LETTER #6

DATE: 05 May 1995

TO: R44 Owners, Operators and Service Centers

SUBJECT: Autorotation RPM Adjustment

ROTORCRAFT AFFECTED: R44 Helicopter S/N 0001 thru 0144

BACKGROUND: The autorotation RPM adjustment chart has been revised based on flight test experience.

COMPLIANCE PROCEDURE:

Verify autorotation RPM using procedure and RPM chart provided in Change 3 of R44 Maintenance Manual, Section 10.250, and adjust if required. Flights should be performed at minimum practical weight.

Approximate Cost:

Parts: None required

Labor: 1 manhour