

**R66 SERVICE LETTER SL-02**

**DATE:** 07 September 2011

**TO:** R66 owners, operators, and maintenance personnel

**SUBJECT:** Baggage Door Seals Kit

**BACKGROUND:** RHC has received reports of water entering the baggage compartment around the edges of the door. A seals kit is available for R66 helicopters S/N 0011 thru 0018, 0021 thru 0028, 0030, 0033, and 0035.

---

**COMPLIANCE PROCEDURE:**

1. Order one KI-207 kit from RHC Customer Service and install per kit instructions. Kit includes seals, tape, angles, rivets, and instructions.

Instructions are available online at [www.robinsonheli.com](http://www.robinsonheli.com) under the Publications tab.

**Approximate Cost:**

Parts: No charge for KI-207 kit if ordered while aircraft is under warranty.

Labor: 1.5 man-hours.