2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

Page 1 of 1

R44 SERVICE LETTER SL-86

DATE: 14 June 2023

TO: R44-series Owners, Operators, & Maintenance Personnel

<u>SUBJECT:</u> Lycoming Electronic Ignition System (EIS) Retrofit Kit for Helicopters with Provisions

BACKGROUND: Retrofit kits are now available for the following helicopters which were built with provisions for Lycoming EIS:

R44 Helicopter S/Ns 2706 thru 2724,

R44 II Helicopter S/Ns 14573, 14574, & 14576 thru 14613, and

R44 Cadet Helicopter S/Ns 30088 & 30089.

COMPLIANCE PROCEDURE:

As desired, order appropriate EIS kit per following table and install per kit instructions:

R44 S/Ns 2706 thru 2724 & R44 Cadet S/Ns 30088 & 30089	R44 II (fuel-injected) S/Ns 14573, 14574, & 14576 thru 14613
Order KI-272-2A Kit	Order KI-272-2B Kit

Order must be received by 31 December 2023, and must include copy (digital photo acceptable) of helicopter's registration indicating helicopter serial number.

Shipping and labor costs are not covered.